



BOSCH

Circular hand saw

5050 TYPE 1 | F 012 505 099

Table of Content

Spare parts list.....	2
Illustration - Type.....	4

Spare parts list

Item	Part Number	Description	Illustration	Price	Quantity	Price Group
1	2 610 904 250	Motor Housing	1	-	1	
2	2 610 341 367	Field 120V	1	-	1	
3	2 610 341 306	Armature 120V	1	-	1	
13	2 610 921 176	Guide Bearing	1	-	1	
18	2 610 996 627	Protective Cap	1	-	1	
19	2 610 341 374	Base	1	-	1	
21	2 610 341 350	Gear Shaft	1	-	1	
23	2 610 341 361	Supporting Disc	1	-	2	
25	2 610 341 255	Sealing cap	1	-	1	
27	2 610 341 377	Cable 385 MM	1	-	1	
28	2 610 341 378	Cable 270 MM	1	-	1	
36	1 619 X01 554	Bearing Plate	1	-	1	
37	2 610 341 359	Spring retaining ring	1	-	1	
38	2 610 341 366	Spacer	1	-	1	
39	2 610 341 394	End stop	1	-	1	
40	2 610 341 465	Washer	1	-	1	
41	2 610 347 486	Extension Spring	1	-	1	
42	2 610 347 892	Spacer	1	-	1	
43	2 610 350 655	Rubber Buffer	1	-	2	
44	2 610 351 898	Lever	1	-	1	
60	2 610 017 262	Round-Head Bolt	1	-	1	
61	2 610 328 924	Screw	1	-	1	
62	2 610 341 335	Screw	1	-	4	
63	1 619 P01 505	Screw	1	-	8	
64	1 619 X01 786	Contact Screw	1	-	3	
65	1 619 X00 935	Hex Screw	1	-	1	
66	2 610 347 100	Screw	1	-	1	
67	2 610 347 103	Screw	1	-	2	
69	2 610 313 808	Washer	1	-	1	
70	2 610 341 332	Slotted Spring Pin	1	-	1	
71	2 610 029 562	Wing Nut	1	-	1	
73	2 610 341 354	Spring retaining ring	1	-	1	
74	2 610 901 987	Lever	1	-	1	
75	2 610 901 988	Nut	1	-	1	
76	1 619 P01 535	Washer	1	-	1	

* Prices shown are net prices including VAT

Spare parts list

Item	Part Number	Description	Illustration	Price	Quantity	Price Group
79	2 610 069 183	Spring Washer	1	-	1	
650	2 610 341 299	Box Wrench	1	-	1	
804	2 610 347 481	On-Off Switch	1	-	1	
805	2 610 313 328	Power supply cord	1	-	1	
810	2 610 993 156	Carbon-Brush Set	1	-	1	
814	2 610 356 680	Spacer	1	-	1	
818	2 610 341 288	groove ball bearing	1	-	1	
829	2 610 341 268	Pivoting Blade Guard	1	-	1	
832	2 610 904 887	Handle	1	-	1	

* Prices shown are net prices including VAT

